

Safety

A WINCO® approved service technician should carry out repairs if necessary. Do not remove any components or service panels on this product.

If the power cord is damaged, it must be replaced by a WINCO® approved service technician in order to avoid a hazard.

	WARNING ⚠️ AVERTISSEMENT
	Electrical Shock Hazard Keep water and other liquids from entering the inside of the unit. Liquid inside the unit could cause an electrical shock.
	Risque de choc électrique Conserver l'eau et d'autres liquides de pénétrer à l'intérieur de l'appareil. Liquide à l'intérieur de l'appareil pourrait provoquer un choc électrique.
	Do not spray water or cleaning products. Liquid could contact the electrical components and cause a short circuit or an electrical shock. Do not use unit if power cord is damaged or has been modified.
	Ne pas pulvériser de l'eau ou des produits de nettoyage. Le liquide pourrait contacter avec les composants électriques et causer un court-circuit ou un choc électrique. Ne pas utiliser l'appareil si le cordon d'alimentation est endommagé ou a été modifié.

Service and Repair

There are no user serviceable parts within this appliance.

To avoid serious injury or damage, **NEVER** attempt to repair the unit yourself.

To initiate warranty service contact

Email: support@wincous.com

Or call: 973-295-3899

DO NOT send the unit to WINCO® until you've contacted our customer service department first.

DIGITAL PORTION SCALE

Operating Instruction Manual



SCAL-D20

*Thank you for purchasing this digital portion scale. Winco® takes pride in the quality of our products. When used as intended and with proper care and maintenance, you will experience years of reliable operation. To ensure the best results, please read and follow the instructions in this manual carefully. **Save these instructions for future reference.***

Specifications

Capacity: 20lbs / 9kg

Increments: oz / g

Tare range: tare full capacity

Auto off: after three (3) minutes of inactivity

Operation temperature: 41°F – 95°F

Display: LCD

Operation (On / Off)

1. Place scale on a horizontal flat surface and press the ON/OFF key.
2. Wait until “0.0” is displayed.
3. Put the object(s) on the weighing platform.

Counting Functions (PCS)

1. Turn the scale on.
2. Flip the scale plate over and place 25, 50, 75, or 100 pieces of the item being counted.
3. Press and hold “PCS” key for two seconds - the number 25, 50, 75 or 100 will show on the screen.
4. Press “MODE” key to select the number of pieces that were placed on the plate, then press the “PCS” key to confirm the selection.
5. Add the remainder of the items that are being counted onto the plate to get the total quantity of items.

Mode

Press the “mode” key to select either **lbs** or **kg** as the desired unit of measurement.

Backlight

Turn the scale on and press the “light” key - this turns on the backlight.

Tare Weighing

1. Turn on scale.
2. Place the “tare item” on the platform.
3. Press “TARE” and wait until “0” is displayed.
4. Add the “net-weight-item”.

Calibration Check

(Must have a calibrated 5 kg or 10 kg weight)

1. Turn the scale on.
2. Press and hold “MODE” key until “CAL” flashes on screen, then 10 kg.
If you have a 5 kg item, press “TARE” until 5 kg flashes.
3. Place calibrated 5 kg or 10 kg weighted item on scale.
4. If scale is calibrated correctly, “PASS” will flash across screen.
5. Remove weight and restart unit with “ON/OFF” key.

NOTE: If “PASS” does not flash across the screen, then the scale was not calibrated correctly or the weight is not weighted properly.

WARNING

- Avoid any exposure to extreme heat or cold. The scale will work better when operated at room temperature... allow the scale to acclimate to room temperature for at least one hour prior to use.
- Keep your scale in a clean environment. Dust, dirt, moisture, vibration, air currents and a close distance to other electronic equipment can all cause an adverse effect on the reliability and accuracy of your scale.
- Handle with care. Place any/all items to be weighed gently onto tray top. This is a precision instrument and should be handled with extreme care.
- Not recommended to plug-in unit and use batteries at the same time.